

- 1. If any part of an A.C. pavement restoration fails, a corrective inlay will be required. The width and length of the inlay will be determined by the City Engineer pursuant to these Standard Drawings.
- 2. In this example, the utility cut or trench is located within an A.C. roadway without a bike lane or parking lane, and there is less than 3 feet between the final pavement cut and the edge of A.C. pavement. Therefore, the permitee shall grind and inlay to the edge of the pavement as shown.
- 3. Where there is 3 feet or more between final pavement cut and edge of A.C. pavement, permitee may "jog" the grind and inlay as shown. The number of jogs shall be kept to a minimum.
- 4. The width of example "A-1" grind/mill and inlay shall be 9 feet minimum, 13 feet maximum.

| City Of Beaverton |
|-------------------|

| <b>ENGINEERING</b> |
|--------------------|
| DEPARTMENT         |

## CORRECTIVE A.C. PAVEMENT INLAY EXAMPLE "A-1" FOR UTILITY CUT OR TRENCH

| CITY ENGINEER       | DATE        | DRAWN BY  | DRAWING NO. |
|---------------------|-------------|-----------|-------------|
| Terry Waldele, P.E. | 6 - 10 - 04 | JCH - CPD | 311         |